

HUSQVARNA MOTORCYCLES RECALLS SVARTPILEN 701, VITPILEN 701, 701 ENDURO, 701 SUPERMOTO OF THE MODEL YEARS 2018-2020

ALL MACHINES TO BE INSPECTED BY AN AUTHORISED HUSQVARNA MOTORCYCLES DEALER DUE TO A POSSIBLE CLUTCH SLAVE CYLINDER ISSUE

Valid for all markets

Husqvarna Motorcycles is recalling all LC4 models (Svartpilen 701, Vitpilen 701, 701 Enduro, 701 Supermoto) of the model years 2018-2020 due to potential damage to the seal in the clutch slave cylinder. Possible deviations in assembly may impair the function of the clutch slave cylinder.

The issue may not be apparent on all motorcycles, however, owners of these models are required to return their machine to an authorised Husqvarna Motorcycles dealer who will inspect and, if needed, replace the clutch slave cylinder.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the Husqvarna Motorcycles website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorised Husqvarna Motorcycles Dealers only.

Further info on all authorised dealers can be found on Husqvarna Motorcycles' website:

<https://www.husqvarna-motorcycles.com/en-int/dealer-search.html>