

PRESS INFORMATION, 25.07.2017

HUSQVARNA MOTORCYCLES ANNOUNCE 2018 OFFROAD MODEL RECALL

MY18 MODELS FEATURING MAGURA BRAKE CALIPERS TO BE CHECKED AT AUTHORISED HUSQVARNA MOTORCYCLES DEALERS

Husqvarna Motorcycles today announce the recall of 2018 FE, TE, FX, TX, FC and TC models for a thorough inspection on their MAGURA brake calipers.

Due to deviations in the manufacturing process at Husqvarna Motorcycles' official supplier, brake caliper assemblies might be incomplete with the anti-rattle plates and cotters possibly missing in the models referred to above.

Therefore, both front and rear calipers on all affected Husqvarna Motorcycles must be inspected for completeness by fully trained technicians.

Customers who own one of the affected motorcycles are being informed by a personal letter and asked to immediately contact an authorised Husqvarna Motorcycles dealer to arrange an appointment for inspection and replacement.

In addition, all Husqvarna owners can check online in the 'Service' area of [Husqvarna Motorcycles' website](http://www.husqvarna-motorcycles.com) to determine if their motorcycle is affected by this recall.

Further info on all authorised dealers can be found on the ['Dealer Section'](#) of Husqvarna Motorcycles' website.

This recall is not affecting US and Canada.



MY18 FE 250



MY18 TC 65

FOR FURTHER INFORMATION, PLEASE CONTACT:

Paolo Carrubba
Head of Media and Public Relations
M + 39 / 347 / 97 18 769
E paolo.carrubba@husqvarna-motorcycles.com