

HUSQVARNA MOTORCYCLES RECALLS MY21 TC, FC AND FS MODELS

ALL MOTOCROSS AND COMPETITION SUPERMOTO MODELS TO BE CHECKED AT AUTHORISED HUSQVARNA MOTORCYCLES DEALERS DUE TO POSSIBLE FITMENT OF DEFECTIVE CHAIN

Valid for all markets

Husqvarna Motorcycles is recalling all model year 2021 TC, FC and FS models in order for authorised Husqvarna Motorcycles dealers to check if a defective drive chain may have been installed due to deviations in manufacturing at our supplier.

While the deviation may not be present on all motorcycles, possible premature failure of the chain can lead to possible consequential damage. The chain must therefore be replaced on all of the affected motorcycles.

Customers who have already acquired one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the Husqvarna Motorcycles website to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorised Husqvarna Motorcycles Dealers only.

Further info on all authorised dealers can be found on Husqvarna Motorcycles' website:

<https://www.husqvarna-motorcycles.com/en-int/dealer-search.html>