

HUSQVARNA MOTORCYCLES RECALLS 2023 FC 250 AND FC 350

ALL 2023 FC 250 AND FC 350 MACHINES TO BE INSPECTED BY AN AUTHORISED HUSQVARNA MOTORCYCLES DEALER FOR POTENTIAL REPLACEMENT OF THE CLUTCH SLAVE CYLINDER

Valid for all markets

Husqvarna Motorcycles is recalling all 2023 FC 250 and FC 350 models due to supplier assembly line variations which may have caused damage to the clutch slave cylinder seal. This may impair its function, and consequently the clutch slave cylinder on all affected vehicles must be inspected and replaced if necessary.

The issue may not be apparent on all motorcycles, however owners of these models must return their machine to an authorised Husqvarna Motorcycles dealer to have the clutch slave cylinder changed as required.

Customers who have already acquired one of the above-named motorcycles are being informed by personal letter and are asked to contact an authorised Husqvarna Motorcycles dealer to arrange an urgent inspection appointment.

In addition, customers can check online in the '[Service](#)' area of the Husqvarna Motorcycles website to determine if their motorcycle is affected by this recall. The inspection and replacement of all affected parts will be carried out at no cost to the customer and must only be performed by authorised Husqvarna Motorcycles dealers.

Further information on all authorised dealers can be found on the Husqvarna Motorcycles website:

<https://www.husqvarna-motorcycles.com/en-int/dealer-search.html>