

HUSQVARNA MOTORCYCLES RECALL SPECIFIC NUMBERS OF FR 450 RALLY MY19 MODELS

Husqvarna Motorcycles are recalling specific numbers of FR 450 Rally machines of model year 2019, in order to replace the rear fuel tank at authorised Husqvarna Motorcycles dealers.

Deviations may have occurred in the production process of the rear fuel tank. As a result, in the area of the fuel pump flange, under certain circumstances, a minimal fuel outlet may occur on one of the screwed inserts. For this reason, the rear fuel tanks on affected vehicles must be replaced.

Replacing the fuel tank takes about 75 minutes and can only be done by an authorised Husqvarna Motorcycles dealer. This action is free of charge for customers.

Customers who already own one of the above-mentioned motorcycles are being informed by a personal letter and are asked to immediately contact an authorised Husqvarna Motorcycles Dealer to arrange an appointment.

In addition, customers can check online in the '[Service](#)' area of the [Husqvarna Motorcycles website](#) to determine if their motorcycle is affected by this recall. The check and replacement of all parts involved will be carried out at no cost to the customer and must be performed by authorized Husqvarna Motorcycles Dealers only.

Further info on all authorised dealers can be found on Husqvarna Motorcycles' website: www.husqvarna-motorcycles.com/dealer-search