

PRESS INFORMATION, 29. 01. 2018

HUSQVARNA MOTORCYCLES ANNOUNCE FS 450 MY16-18 MODEL RECALL

**FS 450 BIKES OF MODEL YEARS 2016, 2017
& 2018 TO BE CHECKED AT AUTHORIZED
HUSQVARNA MOTORCYCLES DEALERS**

VALID FOR ALL MARKETS



FS 450 MY16-18 MODEL RECALL

Husqvarna Motorcycles today announce the recall of 2016, 2017 & 2018 FS 450 machines due to possible deviations in the production process of the Brembo radial brake master cylinders.

An official recall has been made by Brembo SpA, a leader in the production of disc brake systems for vehicles, explaining that possible defects to the piston of the front radial brake master cylinder (diameter 15mm and 16mm) are the reason for all FS 450s needing to be checked.

Customers who own one of the affected motorcycles are being informed by a personal letter and asked to immediately contact an authorised Husqvarna Motorcycles dealer to arrange an appointment for inspection and replacement. All work by authorised Husqvarna Motorcycles dealers will be carried out at no cost to FS 450 owners.

In addition, all Husqvarna owners can check online in the '[Service](#)' area of [Husqvarna Motorcycles' website](#) to determine if their motorcycle is affected by this recall.

Further info on all authorised dealers can be found on the '[Dealer Section](#)' of Husqvarna Motorcycles' website.

FOR FURTHER INFORMATION, PLEASE CONTACT:

Paolo Carrubba

Head of Media and Public Relations

M +39/347/97 18 769

E paolo.carrubba@husqvarna-motorcycles.at