

PRESS INFORMATION, 30.09.2016

## RECALL OF MY2017 HUSQVARNA MOTOCROSS & OFFROAD MODELS

### Valid for all markets

Husqvarna Motorcycles is recalling certain frame numbers of TC, FC, TX, TE and FE models of model year 2017 to authorized Husqvarna dealers for an inspection and, if necessary, replacement of the hand brake cylinder.

Following market investigations by Husqvarna it has been determined that anomalies in the manufacturing process have resulted, with certain batches, in hand brake cylinders with defective machining from the supplier. This can lead to early wear of the sealing cup in the hand brake cylinder, thus leading to impaired braking performance. As the anomalies are restricted to specific batches, the hand brake cylinder must be checked and the affected batches replaced.

The following models are affected by the recall (the list may vary based on country specification)

TC 125  
TC 250  
FC 350  
FC 450

TX 125  
TE 250  
TE 300  
TX 300  
FE 250  
FE 350  
FE 450  
FE 501

Owners of affected motorcycles will be informed by a personal letter and are asked to immediately contact an authorized Husqvarna Motorcycles dealer to arrange an appointment for inspection. In addition, customers can check online in the [‘Service’](#) area of the [Husqvarna Motorcycles website](#) to determine if their motorcycle is affected by this recall.

The check and/or replacement of the hand brake cylinder will be carried out at no cost to motorcycle owners, but must be performed by authorized Husqvarna dealers only.

### FOR FURTHER INFORMATION, PLEASE CONTACT:

**Paolo Carrubba**  
Head of Media and Public Relations  
M + 39 / 347 / 97 18 769  
E [paolo.carrubba@husqvarna-motorcycles.com](mailto:paolo.carrubba@husqvarna-motorcycles.com)



MY17 FE 350